




Sealco Commercial Vehicle Products

215 East Watkins Street Phoenix, Arizona 85004 602/253-1007 Fax 800/222-2334



Control Tube	Service Hose	Other	1/2" Diameter
Supply Tube	Spring Hose		5/8" Diameter

No.	Description	No.	Description
1	110800 Spring Brake Valve	10	#616 1/2" x 3/4" Nipple Or #6024 1/2" x 1/2" Nipple
2	400 500 104 0 2s1m ABS Relay Valve	11	#616 1/2" x 3/4" Nipple Or #6006 3/4" x 3/4" Nipple
3	2550 Supply Filter (Optional)		
4	432 500 005 0 Control Line Filter (Optional)		
5	110570 Control Line Booster Valve		
6	10200 1/2 Check Valve		



Unless otherwise noted all hose is 3/8", supply line tube 1/2" & control line tube 3/8".

This design may not comply with performance requirements such as timing, grade holding or application. Compliance with these and all other applicable regulations are the responsibility of the vehicle manufacturer.

Air System Requested By

...

2s1m Tandem Axle Dolly

DR: ZY	CH: DH	Date Jun. 13, 2008	Drawing Number P-6662
-----------	-----------	-----------------------	--------------------------